

# **GATING AND RISERING**

**Rahul Singh Yadav**

Assistant Professor

Department of mechanical Engineering


Vision institute of Technology

# CONCEPT OF GATING AND RISERING

- DEFINTION
- TYPES OF GATES
- GATING DESIGN
- GATING RATIO
- RISERING
- TYPES
- FUNCTIONS

# ELEMENTS OF GATING SYSTEM

1. Pouring basin
2. Down sprue
3. Sprue base
4. Runner
5. Runner Extension
6. Gates




# GATING

- Gating are flow passages to run and fill molten metal in mould cavity.
- Gating system include distribution of clean metal with proper rates and velocities at specific location in the mould.

# TYPES OF GATING SYSTEM


- Top gate
- Bottom gate
- Branch gate
- Horn gate
- Parting type

# Top gate




- Molten metal from pouring basin is fed directly into the mould cavity.
- The hottest metal remains at the top of casting , this promotes directional solidification from the casting towards the gate

# Bottom gate



- **The molten metal enters from bottom to the mould cavity.**
- **It minimizes turbulence and erosion in the mould cavity.**
- **Provides unfavorable temperature gradients that do not promote directional solidification.**


# Horn gate



- This type of gate which is a part of the pattern with smooth curves and progressive change in dimension is designed to minimize mould erosion and oxidation of molten metal.



## Parting type



- It is most commonly used gate and is a compromise between top and bottom gates.
- The gate is provided at the parting line of the mould .

# Risering


- A riser or feeder head is a vertical passage made in the cope to store the liquid metal and supply the same to the casting as it solidifies.

## **Functions:**

- Store sufficient liquid metal and supply the same to the casting it solidifies there by avoiding volumetric shrinkage of the casting.
- The riser must be kept open to the atmosphere and placed in such a location that it maintains a positive pressure of liquid metal on all portions of the casting it is intended to feed.
- The cylindrical shaped riser are generally recommended compared to spherical shaped risers which although consider as the best.


# Types of riser

## 1. Open riser / Top riser



- The top surface of the riser will be open to the atmosphere.
- The open riser is usually placed on the top of the casting.
- Gravity and atmospheric pressure causes the liquid metal in the riser to flow into the solidifying casting.

## 2. Blinder riser/ Side riser



- It is completely enclosed in the mould and not exposed to the atmosphere .
- The metals cools slower and stay longer promoting directional solidification.
- The liquid metal is fed to solidifying casting under the force of gravity alone.



# Solidification Time For Casting

- Solidification of casting occurs **by losing heat from the surfaces** and amount of heat is given by volume of casting .
- **Cooling characteristics** of a casting is the ratio of **surface area to volume**.
- Higher the value of **cooling characteristics** **faster is the cooling of casting**.

Chvorinov rule state that **solidification time is inversely proportional to cooling characteristics**.

Solidification time

$$t_s = K \left( \frac{V}{SA} \right)^2$$

Where

$T_s$  = Solidification time

$V$  = Volume of casting

$SA$  = Surface area

$K$  = mould constant

① Condition for minimum surface area & max solidification time in case of cylindrical riser

1- side view

$$SA = 2\frac{\pi}{4}d^2 + \pi dh \quad \text{--- ①}$$

$$V = \frac{\pi}{4}d^2h \quad h = \frac{4V}{\pi d^2} \quad \left| \begin{array}{l} h \text{ put in} \\ \text{eqn ①} \end{array} \right.$$

$$SA = 2\frac{\pi}{4}d^2 + \pi d \left( \frac{4V}{\pi d^2} \right)$$

$$SA = \frac{\pi}{2}d^2 + \frac{4V}{d}$$

$$\frac{dSA}{dd} = 0$$

$$= \pi d - \frac{4V}{d^2} = 0$$

$$V = \frac{\pi d^3}{4} = \frac{\pi}{4}d^2h \quad \boxed{h=d}$$

$$\frac{SA}{V} = \frac{2\frac{\pi}{4}d^2 + \pi dh}{\frac{\pi}{4}d^2h} \quad h=d$$

$$\boxed{\frac{SA}{V} = \frac{6}{d}}$$

$$\text{Topriker} = SA = \frac{\pi}{4} d^2 + \pi d h \quad \text{--- (1)}$$

$$V = \frac{\pi}{4} d^2 h \Rightarrow h = \frac{4V}{\pi d^2}$$

$$SA = \frac{\pi}{4} d^2 + \pi d \frac{4V}{\pi d^2}$$

$$SA = \frac{\pi}{4} d^2 + \frac{4V}{d}$$

$$\frac{\partial SA}{\partial d} = 0$$

$$\frac{\pi d}{2} - \frac{4V}{d^2} = 0$$

$$V = \frac{\pi d^3}{8} = \frac{\pi}{4} d^2 h$$

$$\boxed{h = \frac{d}{2}}$$

$$\frac{SA}{V} = \frac{\frac{\pi}{4} d^2 + \pi d h}{\frac{\pi}{4} d^2 h}$$

$$\boxed{h = \frac{d}{2}}$$

$$\delta l = l \alpha \Delta T$$

Pr $\rightarrow$  In a cubical casting of 50mm size under goes volumetric solid contraction of 6%. & volumetric solidification contraction of 6%. & volumetric solidification shrinkage of 4%. There of No. of is used for pattern making allowance is not considered what is the final size of the casting.

Solve  $\rightarrow$

$$\text{Volume of material} = a^3 = 50^3 \text{ mm}^3$$

$$\text{Volume of material C} = 50^3 \times 0.94$$

$$\text{Volume of material P} = (50^3 \times 0.94) \times 0.94$$

$$a^3 = 112800 \text{ mm}^3$$

$$a = 48.31 \text{ mm}$$



Thank

you

